

1991 ALFA ROMEO SPIDER AUTOMATIC

This is what has been worked on or replaced in the last 2 calendar years:

1. New radiator \$219
2. New upper and lower radiator hoses \$44 + \$38
3. Lower manifold water bypass hose \$67
4. New thermostat \$40
5. Spare new water pump \$68
6. Repaired wiring to fans
7. New thermal switch in radiator \$9
8. Replaced power steering hoses to the steering cooler \$38
9. Cleaned and painted headers
10. Valve job including new seats, guides, seals \$380 *labor*
11. Intake and exhaust valves \$100
12. New guides/seals \$90
13. New Head gasket set \$33
14. New valve cover gasket and bolt seals
15. Viton O-rings for the head gasket
16. New thermo sensor in intake manifold \$10
17. Cleaned and serviced injectors \$100
18. Replaced the injectors that were leaking \$110
19. New injector connectors 5 x \$19 \$75
20. New hoses and clamps
21. Cleaned intake manifold and air plenum
22. New fuel pressure regulator \$88
23. New rubber support for air plenum *from spares*
24. New cap, rotor and wires \$145
25. New throttle cable \$40
26. New spark plugs (BP6EIX) \$36
27. Changed oil and filter \$50 *synthetic 20-50*
28. Changed oil in transmission (5 x \$7.50) \$37.50
29. Changed oil in rear axle
30. New oil pressure sender \$80
31. New brake pads front/rear \$46 + \$43
32. New braided brake lines (3) \$82
33. Rebuilt calipers with new seal kits \$40
34. New inner/outer wheel bearings and seals \$100
35. New fuel tank evaporator purge valve \$25
36. Replaced brake vacuum line \$38
37. New master cylinder \$80
38. New in tank fuel pump \$72.50
39. Replaced brake vacuum valve *from spares*
40. Rewired the starter wires to be factory correct
41. New battery \$75 *Costco*
42. Rear tail lights replaced, cleaned and connections checked (original set comes with car)
43. Front head lights removed and connections cleaned
44. Repaired connectors on the starter inhibitor switch

45. Checked all the side marker lights to work
46. Found A/C bracket \$100
47. New power steering hose (low pressure) \$5 + \$14 fluid
48. Replaced steering wheel
49. Replaced steering wheel air bag (original comes with the car)
50. Installed factory hard top \$800 * shipped from Canada*
51. Replaced door panels from a 1990 Veloce spider (non alcantara) \$300
52. Replaced seats from a 1990 Veloce spider (non alcantara) Original seats come with the car)
53. New door clips \$46.60
54. Have a spare automatic transmission 80,000 and works perfectly, with drive shaft, support, shifter, torque converter, hoses and cooler- (included with sale @ no charge)
55. Transmission serviced with new filter and gasket (spare kit comes with the car)
56. Fill tube seals replaced at pan to stop weeping.
57. Transmission cooler hose seals replaced at transmission to stop weeping.
58. Repaired broken wire at transmission transducer for speedometer head
59. Replaced all the lights in the instrument quadrant, cleaned all contacts
60. New windshield and gasket \$130 + \$90 +\$60 install
61. Both door glass and cables lubricated and adjusted to work optimally
62. New water seal drapes installed in the door
63. Air flow meter replaced \$100
64. All electrical connections removed, cleaned and replaced with DeOxit D5 and DeOxit gold
65. Ground connections cleaned, new star washers, DeOxit D5 and sealed everywhere on the car
66. New driver's door mirror \$230
67. Paint for mirror \$84
68. New script for the rear panel
69. Cleaned the oil vapor separator
70. Replaced brake booster
71. New motor mounts \$76
72. Tires – 4 new Bridgestone *Costco*
73. \$400 Powder coated 5 rims \$375
74. Replaced non-operating headlights
75. Replaced broken or missing exhaust hangers \$5
76. Replaced rear muffler
77. New brake pedal pad (comes with spare) \$20
78. All receipts for the car for work and parts
79. Original owner's manual
80. Paper work from the previous owners
81. California title and bill of sale from previous owner and bill of sale from me
82. New KYB shock absorbers, adjustable upper A arms,
83. 4 speaker door covers
84. Original owner's manual
85. New Covercraft car cover \$180

NEEDS:

- Power antenna
- AC pump, and hose replaced and recharged.
- Soft-top (original) no holes - bad back window
- Windshield washer squirters
- Windshield wipers (have the arms)
- Speakers for the doors
- Dashboard
- Exhaust system- no catalytic converter.
- Single stage paint color sanded and buffed out
- Receipts for most everything

Total approximately invested for the car, parts and services \$13,000